

Welcome to Steinberg's Timebase

Thanks for choosing Timebase. This Readme contains important information about the product. Please read the following text carefully.

DRIVER SOFTWARE INSTALLATION:

Windows PC Drivers

When you connect Time Base to your computer for the first time, Windows will recognize the new hardware component and start its "Add New Hardware Wizard".

1. Insert the Driver CD into your CD-ROM drive and follow the instructions displayed on your computer screen. The necessary driver software – a Firmware Loader and the actual Time Base driver – will now be installed during two separate installation processes. (Note: You can safely ignore alert messages like "Digital signature not found", "Do not install driver", "Driver not certified". Simply continue with the installation.)
2. Restart your computer when the installation procedure has been completed.

Mac OS X Drivers

When you have connected the hardware for the first time and started the computer, you can install the driver software from the Driver CD-ROM.

1. Start driver installation by double clicking on the Time Base Driver icon.
2. Follow the instructions on the screen and restart your computer when the procedure has been completed.

DOCUMENTATION:

Steinberg is proud to provide customers with a printed manual for Timebase. In addition, electronic documentation is included on the driver CD that came with the product.